

**ANACONDA Copper Company**


New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



*dcj*  
*10/11*  
*198*  
*MN*

June 7, 1979

A. F. Czarnowsky  
Area Mining Supervisor  
United States Geological Survey  
P. O. Box 26124  
Albuquerque, N.M. 87125



Dear Mr. Czarnowsky:

The following information is being submitted in accordance with the Jackpile Mine Reclamation Sampling Plan.

1. Radiological and chemical analysis of reclamation site soils.
2. Surface gamma emission from reclaimed sites.
3. Radon exhalation values from reclaimed sites.

*Christopher Sanchez*  
Christopher Sanchez  
Reclamation Engineer

cc: RDL  
MAS  
ECL  
EAL  
file